

(SUBMIT IN TRIPLICATE)
**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No. 07922
Unit Bolack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 16, 1958

Well No. 16-C is located 210 ft. from [N] line and 990 ft. from [E] line of sec. 33
RT Sec. 33 27N 04W H.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco M.V. Ext. San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6751 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-15-58. Total Depth 5203'.

Ran 4 joints 5 1/2", 15.50#, J-55 casing (2402') set from 2873' to 5273' with 125 sacks regular cement, 125 sacks Pozmix, 4 gal, 1/8" Floceles/gal, followed by 50 sacks Best cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 2873'



I understand that this plan of work must receive approval in writing by the Geological Survey, before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 991

Farmington, New Mexico

By Original Signed D. C. Johnston

Title Petroleum Engineer

