


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe
Lease No. E M 03603 A
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

JAN 28 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 21

19 59

Well No. 6 is located 750 ft. from N line and 1870 ft. from E line of sec. 25
SE 25 (4 Sec. and Sec. No.) T7N (Twp.) R1E (Range) 104W (Meridian)
So. Kansas (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 9986.5 ft. R B

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

January 5, 1959

Perforate 2136-2202, 31 shots
 Fracture 52635 G. Water, Flush 3525 G, 200 G 15% acid
 BDF 1800', Treat Fr 1800', Rate 69.2 BPM
 Sand 45000'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company John A. Egan
 Address Box 1206
Farmington, New Mexico
 By Original Signed John A. Egan
 Title Operator