



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 079232  
Unit Bolack

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

MAY 7

1958

U.S. GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 7, 1958

Well No. 13-C is located 960 ft. from S line and 800 ft. from W line of sec. 29

SW Sec. 29

(1/4 Sec. and Sec. No.)

27N

(Twp.)

ON

(Range)

R.M.P.M.

(Meridian)

Blanco Est. 480. Blanco P.C.

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 6395 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-20-53. Total Depth 4830'.

Run 14 joints 5 1/2", 15.50#, J-55 casing (451') set from 4374' to 4825' with 75 sacks regular cement, 75 sacks Pozmix, 6% gal. 1/8# Floccula/sk, followed by 50 sacks best cement.

Hold 1000# for 30 minutes.

Top of cement by temperature survey at 4374'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By

Original Signed P. H. WOOD

Title Petroleum Engineer

