



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 37522
Unit Solack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 3, 1958

Well No. 5-3 is located 1150 ft. from S line and 1750 ft. from E line of sec. 30
30 (1/4 Sec. and Sec. No.) 27N (Twp.) 9W (Range) 104W (Meridian)
San Blanco P.M. (Field) San Juan (County or Subdivisor) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6103 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-3-58. Total depth 2140'.
Run 3 joints of 1 1/2", 15.5 lb., J-55 casing (2130') set at 2140' with 75 sacks
regular cement, 75 sacks Ramix, 45 gal.
Hold 1000# for 30 minutes.
Log at cement of temperature curve, at 1330'.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company
Address P.O. Box 127
Permian Basin, New Mexico
By [Signature]
Title Petroleum Engineer

