

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078092

Unit SR 26 is

Designated Drilling Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 2

1952

Well No. Douthit is located 990 ft. from S line and 990 ft. from E line of sec. 26

SR 26 (Sec. and Sec. No.) 27 N (Twp.) 11 W (Range) N. 4. 30. W. (Meridian)

So Rutz Canyon Ext. (File) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6189 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 20 72 Top. P.C. 2055 ran 69 Qts. J55, 1 1/2" Pipe
Set Pipe at 2060 Cemented with 75 sac Reg. Cement 2%
Calcium Chloride, Temp. Survey Shows cement top at 1530.
Below Datum tested pipe for 8 hrs. after Plug was drilled.
No water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company British America Oil Prod. Co.

Address Box 3187

Okl. City Oklahoma

By W. L. Latham

Title Assistant Manager