

LOG OF OIL OR GAS WELL

LOCATE WELL CORRECTLY

Company El Paso Natural Gas Company Address Box 997, Farmington, New Mexico
Lessor or Tract Huerfano Unit Field Fulcher-Kutz State New Mexico
Well No. 37-28 Sec. 28 T. 27N R. 9W Meridian N.M.P.M. County San Juan
Location 1475 ft. N. of S Line and 1555 ft. E. of W Line of Section 28 Elevation 6452'
90 100

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Date January 28, 1959 Title Petroleum Engineer

The summary on this page is for the condition of the well at above date.

Commenced drilling Jan. 7, 1956 Finished drilling _____, 19____

OIL OR GAS SANDS OR ZONES

(Denote gas by G)

No. 1, from _____ to _____ No. 4, from _____ to _____
 No. 2, from _____ to _____ No. 5, from _____ to _____
 No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from _____ to _____ No. 3, from _____ to _____
No. 2, from _____ to _____ No. 4, from _____ to _____

CASING RECORD

[illegible]

MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
8 5/8"	100'	70	Pump Plug		

PLUGS AND ADAPTERS

Heaving plug—Material Length Depth set

Adapters—Material Size

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet.

Cable tools were used from 0 feet to 100 feet, and from _____ feet to _____ feet.

DATES

Temp. Abandon Jan. 9 1956 Put to producing _____, 19____

The production for the first 24 hours was barrels of fluid of which% was oil;% emulsion;% water; and% sediment. Gravity, °Bé.

If gas well, cu. ft. per 24 hours Gallons gasoline per 1,000 cu. ft. of gas

Rock pressure, lbs. per sq. in. -----

EMPLOYEES

_____, Driller _____, Driller
_____, Driller _____, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION

