



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SANTA FE
Lease No. 077384
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	X	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JUNE 11, 1956

Well No. 1 is located 1830 ft. from N line and 870 ft. from E line of sec. 30

NE Sec. 30 27N 10W N. 4 P. 4
(E. Sec. and Sec. No.) (Twp.) (Range) (Meridian)
FULCHER - KUTZ SAN JUAN NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5976 ft. G.L. 5969

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SHOOT WELL IN OPEN HOLE FROM 1647' TO 1674'
W/4000 NITRO - 7" O.D. Csg. SET @ 1647'
CUTO. W/100 SZ. REGULAR CEMENT-

FRAC WELL IN OPEN HOLE AS SHOWN ABOVE W/25,000'
20 - 40 SZ. - 680 BBL. WATER

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company FAIRMONT OIL COMPANY, INC.

Address P. O. Box 936

FARMINGTON, NEW MEXICO

By [Signature]

Title SUP.