

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SF 077943-4
Unit C. A. McAdams "B"

RECEIVED
JUL 27 1959
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C. A. McAdams "B"

Farmington, New Mexico

July 23, 1959

Well No. 2 is located 1850 ft. from N line and 750 ft. from W line of sec. 28

NW 1/4 of Section 28

T-27-N

R-10-W

100°W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Angels Peak Dakota

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6038 ft. (GL)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate in case of cobbles, cementing points, and all other important proposed work)

Landed 2" Dakota tubing at 6260' tested with 1900 psi for 30 minutes which held OK. Landed 2" Gallup tubing at 5823'. Dually completed well as SI Angels Peak Gallup oil well and SI Angels Peak Dakota gas well 7-19-59. Potential test Gallup pumped 148 HOD, 12-44" SPN with 1-1/4" pump. On Gallup packer leakage test 7-11-59 Dakota starting 3 day SITP 1924 psig and ending 4 day SITP 1944 psig, indicating packer holding. Dakota potential test 7-16-59 flowed 2570 MCFD after 3 hours thru 3/4" choke. On Dakota packer leakage test 7-16-59, Gallup starting 3 day SITP 1124 psig and ending SITP 1146 psig, indicating packer holding OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PAN AMERICAN PETROLEUM CORPORATIONAddress Box 487Farmington, New MexicoAttention: L. O. Spoor, Jr.

ORIGINAL SIGNED BY

R. M. Bauer, Jr.

By

Title Area Engineer

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45