



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Monte Fe
Lease No. 079114
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

OCT 20 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. 1 is located 1850 ft. from [N] line and 1850 ft. from [E] line of sec. 25
34/4 N 4 Sec 25 27N 12E N 4 W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6042 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 9/1/59 at 3:00 P.M., drilled to Total depth of 236' and ran 8 5/8" 24 # 1 ft. new seamless casing to 236 and circulated cement to surface using 125 sax. Drilled plug. Pipe tested o.k. Secured drilling operators.
(This notice submitted at request of Farmington office U.S.G.S. to verify previous operators of well by Alex B. Campbell.)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Eastern Development Company of Delaware

Address Post Office Box 427

Artesia, New Mexico

By [Signature]

Title [Signature]