

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 317951
Unit Jack Frost

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 2400 ft. from [N] line and 700 ft. from [E] line of sec. 26
1/4 of section 26 (1/4 Sec. and Sec. No.)
Fulcher (Field)
Santa Fe (County or Subdivision)
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6222 ft. (G.C.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled 6100 ft., October 1, 1951.
On October 6, 1951, 12-3/4" casing was landed at 105 feet and cemented with 100 sacks cement. Cement circulated to surface. Plug down at 6:30 A.M., October 6, 1951. At 6:30 A.M. October 7, 1951, casing and water shut-off were tested with 200 lbs. for 30 minutes. No drop in pressure. Forty-three feet of solid cement was drilled in bottom of hole and water shut-off tested with 200 lbs. for 30 minutes. No drop in pressure. Drilling operations were resumed.


I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company American Oil and Gas Company

Address Box 187
Farmington, New Mexico

By [Signature]
Title Production Manager

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF SHOOTING OR ABANDONING
NOTICE OF INTENTION TO SHOOT OR REPAIR	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHUT-OFF	SUBSEQUENT REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY	

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

10

is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State nature of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate no. of rods, joints, and connections; and all other important proposed work)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company _____

Address _____

By _____

Title _____