


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Juan Co.
Lease No. 77951
Unit Jack Frost



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~Farlington, New Mexico~~, ~~November 13, 1951~~
Well No. 2-1 is located 1650 ft. from [N] line and 990 ft. from [E] line of sec. 36
24 1/4 of Section 36 (1/4 Sec. and Sec. No.) 2-27-N (Twp.) 1-10-E (Range) 1-10-E (Meridian)
Farleton-Data (N) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6257 ft. (G.L.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On October 13, 1951, at 3:00 P.M., 5 1/2" casing was landed at 1344 feet with 73 sacks of cement. Rotary tools were moved off and cable tools moved on to drill cement plug and pay. On November 6, 1951, bailed hole dry and remained dry for 2 hours. Drilled 46 feet of solid cement in bottom of pipe and again bailed dry. Hole remained dry for 3 hours which was considered a satisfactory water shut-off test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan Oil and Gas Company
Address Box 427
Farlington, New Mexico
By [Signature]
Title Production Foreman

100-443887-100

211

[illegible]

... car la unit [3] mod. 11 bus anti [2] met. 13 ... botei la ...

[illegible]

The elevation of the bank floor above the level of the

DETAILED WORK

REPORTS OF WORK

I understand that this plan of work must receive approval from the Geological Survey before operations can be started.

Company _____

Address _____

By _____

Title _____