Form 9-381 a (Feb. 1951)			

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	NM 078480
Unit	

	
SUNDRY NOTICES A	ND REPORTS ON WELLS ED
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING ON ACIDIZANGL
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING YEW MEXICO
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Surface Pipe X
(INDICATE ABOVE BY CHECK MARK N	NATURE OF REPORT, NOTICE, OR OTHER DATA)
	October 2 19 58
Hammond	
Well No. 4 is located 990 ft. from	$\begin{Bmatrix} \mathbf{N} \\ \mathbf{S} \end{Bmatrix}$ line and 1650 ft. from $\begin{Bmatrix} \mathbf{K} \\ \mathbf{W} \end{Bmatrix}$ line of sec. 26
1 26 27−N	8-W NMPM
•	Range) (Meridian)
So. Blanco Pictured Cliffs San J	NAN New Mexico Subdivision) (State or Territory)
The elevation of the derrick floor above sea leve	el is ft. 5962' G.L.
DETAIL	S OF WORK
(State names of and expected depths to objective sands; show sizes ing points, and all oth	, weights, and lengths of proposed casings; indicate mudding jobs, coment- er important proposed work)
	,
Spudded well w/surface spudder on Sept Set 86° of 8 5/8° 0.D. 25.65# Grade "B' Cemented pipe w/70 sx neat cement on St to surface. Tested pipe on September :	" Smls casing in 12 1/4" hole at 95.5".
	A. A. Com COM
I understand that this plan of work must receive approval in w	riting by the Caplogias Curvey before operations may be commenced.
Company WESTERN NATURAL GAS COM	PANY
Address 211 W. Main	
	By Calvin M. Sayes
Farmington, New Mexico	By alow M. Nayes
	Title Petroleum Engineer

. .



•