


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 07232  
Unit Bolack



RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS JUN 13 1958  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 16, 1958

Well No. 14-C (PM) is located 800 ft. from N line and 1640 ft. from E line of sec. 30

NE Sec. 30 27N 9W H.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Blanco Ent. & So. Blanco San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)  
P.C.

The elevation of the derrick floor above sea level is 6100 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-8-58. Total Depth 4568'.

Ran 61 joints 5 1/2", 15.50#, J-55 liner (2349') set from 2210' to 4550' with 125 sacks regular cement, 125 sacks Pozmix, 64 gal, 1/8" Floceles/sk followed by 50 sacks Neat cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 3000'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company  
Address Box 997  
Farmington, New Mexico  
By Original Signed D. C. Johnston  
Title Petroleum Engineer