

(SUBMIT IN TRIPLICATE)

Land Office	Santa Fe
Lease No	077951
Unit	

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
	The state of the s
NOTICE OF INTENTION TO CHANGE PL	of officering of Acidizing
NOTICE OF INTENTION TO TEST WATER	
NOTICE OF INTENTION TO RE-DRILL O	
NOTICE OF INTENTION TO SHOOT OR	
NOTICE OF INTENTION TO PULL OR AL	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON W	YELL.
(INDICATE	E ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
Turner-Frost	March 18, 1953, 19
Well No is locate	ed ft. from $\begin{bmatrix} N \\ S \end{bmatrix}$ line and ft. from $\begin{bmatrix} W \\ W \end{bmatrix}$ line of sec. 25
NW/4 Sec. 25	Twp. 27N R 10W
Ta s a /1/ See and See Ma	BAMAP W
Fulcher Stand See No.	(Twp.) (Range) (Meridian) San Juan County New Movies
(Field)	TOW INCATED
	(County or Subdivision) (State or Territory)
	10, 1953.
After waiting for cement Pressure held for 30 min	t to set, tested for water shut-aff with 500 psig. nutes with no indicated drop.
After waiting for cement Pressure held for 30 min	t to set, tested for water shut-sif with 500 psig. nutes with no indicated drop. with 7-7/8" bit.
After waiting for cement Pressure held for 30 min	to set, tested for water shut-siff with 500 psig. nutes with no indicated drop. with 7-7/8" bit. MAR MAR Indicated provide the Geological Survey before operations may be commended to the contract of the
After waiting for cement Pressure held for 30 min Drilling then continued I understand that this plan of work m J. Glenn Tur	to set, tested for water shut-sif with 500 psig. nutes with no indicated drop. with 7-7/8" bit. RELEVEN MAR MAR THE THE PROPERTY OF THE
After waiting for cement Pressure held for 30 min Drilling then continued I understand that this plan of work m J. Glenn Tur Company c/o San Juan Drillin Address Box 728 - Farmin	to set, tested for water shut-siff with 500 psig. mutes with no indicated drop. With 7-7/8" bit. MAR I MA
After waiting for cement Pressure held for 30 min Drilling then continued I understand that this plan of work m J. Glenn Tur Company c/o San Juan Drilling Address Box 728 - Farming me Office: 1711 Mercanti	to set, tested for water shut-siff with 500 psig. mutes with no indicated drop. with 7-7/8" bit. REFINA MAR I
After waiting for cement Pressure held for 30 min Drilling then continued I understand that this plan of work m J. Glenn Tur Company c/o San Juan Drillin Address Box 728 - Farmin	to set, tested for water shut-siff with 500 psig. mutes with no indicated drop. with 7-7/8" bit. REFINA MAR Indicated drop. MAR In

U. S. GOVERNMENT PRINTING OFFICE 16-8437-4

IL CONSERVAT	ION COMMISSION
	TRICT OFFICE
Vo. Copies Recei	ved &
DISTR	IBUTION
	NO. FURNISHED
Operator	
Santa Fe	
Proration Office	
State Land Office	
1) S. G. S.	
Transportor	
Fila	

.