

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

RECEIVED

APR 03 1990

2. Operator  
Meridian Oil Inc.

OIL CON. DIV.  
DIST. 3

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499

4. Location of Well  
790'N, 890'W

5. Lease Number  
SE-077386A SF-077951-A

6. If Indian, All or  
Tribe Name

7. Unit Agreement Name

8. Farm or Lease Name  
Rowley D

9. Well No.  
1

10. Field, Pool, Wildcat  
Basin Fruitland Coal

11. Sec. T. R. M. or Blk  
Sec. 27, T-27-N, R-10-W  
NMPM

14. Permit No.

15. Elevations  
6128' GR

12. County  
San Juan

13. State  
NM

16. Intent to/Subsequent Report of : Re-Perforate

17. Describe proposed or completed operations:

10-23-89 MOL & RU. Kill well w/wtr. Nd WH. Nu BOP. Tooh w/tbg. Ran CCL, GR-N. Tooh. Pu & rih w/2 3/8" tbg. Tag btm @ 1891'. SDON.

10-24-89 Spot 250 gal 7.5% HCL 1891-1641'. Perf'd 1626-27', 1689-91', 1725-40', 1759-72', 1851-65', 1879-81', 1885-91' w/4 spf. Pu SAP tool. Tih, break down perfs. Tooh. Ld tool. Tih w/62 jts 2 3/8" tbg. Swabbed. Ran 2 3/8", 4.7#, J-55, 8rd, EUE tbg landed @ 1860', seating nipple 1 jt off btm @ 1830'. Swabbed.

10-25-89 Cut off bad sand line, poured new rope socket. Started swab, hit fluid level @ 250' from btm. Tbg separated from hanger. Tih, fished tbg. Replaced bad top jt, swabbed, could not get below 1100'. Tooh w/tbg. Tbg damaged in fall to btm. Replaced 30 jts. Tih, tag cmt retainer @ 1891'. Swabbed. Blew well around. Landed 2 3/8" tbg @ 1876', seating nipple 1 jt off btm @ 1844'. Nd BOP. Nu WH. Rig released.

18. Authorized by: Perry B. Shufeldt  
Regulatory Affairs

2-22-90  
Date

NOTE: This format is issued in lieu of US BLM Form 3160-5

Accepted For Record

MAR 17 1990

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY: \_\_\_\_\_

MA  
DATE

