

5-USGS
1-WD
1-D
1-F

SWP-111

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **NE-056364**
Unit _____
Campbell Federal "B"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 5, 1962

Well No. 1 is located 790 ft. from (N) line and 790 ft. from (E) line of sec. 28
NE/4 NE/4 Sec. 28 27 N 12 W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5823.8 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10/3/62 Rigged up Bedford Inc., pulling unit.
10/4/62 Shot casing @ 4873', could not pull loose. Shot casing loose @ 4842'. Spotted 40 sx cement plug 4768-4663.
10/5/62 Recovered 152 fts. 4 1/2" 10.50# casing. Spotted 50 sx cement plug 1178-1048'. Set 30' cement plug @ surface with marker. Well plugged and abandoned 10/4/62.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southwest Production Company

Address 207 Petr. Club Plaza
Farmington, New Mexico

Original signed by
By Carl W. Smith

Title Superintendent