


Form 9-881a
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe
Lease No. NM - 03605
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 23, 1957

Well No. R & O #39 is located 1805 ft. from N line and 1590 ft. from W line of sec. 23

SW/4, Sec. 23 T27N R8W N M P M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
S. Blanco P.C. San Juan N.M.
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 5944 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Casing sundry:

- 8-5/8" surface casing - 171' with 100 sacks cement
- 5-1/2" production casing - 2225', with 200 sacks cement
- 1" tubing at 2150'



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R & O Drilling Co., Inc.

Address 250 West 57th St.

New York 19, N.Y.

By A. Schwartz

Title office mgr.
