

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

APPROVED JUNE 14, 1951  
(Signed) P. T. McGRATH  
DIST. ENGR.

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 77952  
Unit J. C. Gordon

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Parlington, New Mexico June 12, 1951

Well No. C-2 is located 1700 ft. from S line and 1650 ft. from W line of sec. 23

34/4 of section 23 T-27-N 5-1-E N35W  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Fulcher-Euts San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6300 ft. (Est.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was opened 8:00 A.M. June 7, 1951.  
On June 7, 1951, 10-3/4" casing was landed at 101 feet and cemented with 85 sacks.  
Circulation was lost while cementing and cement failed to circulate to surface.  
Plug down at 10:00 A.M., June 8, 1951. Located top cement outside of pipe 11 feet from surface. Recemented through 1-1/4" pipe with 47 sacks cement. Cemented to surface 10:30 A.M., June 8, 1951. After 24 hours tested casing with 300 lbs. for 30 minutes. No drop in pressure. Drilled 33 feet solid cement, tested below casing with 300 lbs. for 30 minutes. O.K. Drilling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box 487

Parlington, New Mexico

By L. O. Spencer

Title Production Foreman