


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. NM 078478

Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

OCT 8 1958

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Production Csg. <u>X</u>

U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 6, 1958

Well No. 5 is located 1750 ft. from [N] line and 890 ft. from [E] line of sec. 23

NE 1/4 23 27-N 8-W NM 078478
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

So. Blanco Pictured Cliffs San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5984' G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 7 7/8" hole to total depth of 2331'. Set 55 jts (2302.85') of 5 1/2" O.D. 15.5# J-55 casing on bottom @ 2331'. Total pipe of 56 jts measured 2347.78'. Cemented pipe w/150 sr most cement on October 1, 1958. Tested pipe w/1000# for 30 min. Held O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WESTERN NATURAL GAS COMPANY

Address 211 1/2 West Main

Farmington, New Mexico

By Calvin M. Rayen

Title Petroleum Engineer

