

EPFS

EL PASO FIELD SERVICES

FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: <u>72368</u> Location: <u>Marathon Fed No 5</u> Operator #: <u>0286</u> Operator Name: <u>Canoe</u> P/L District: <u>Blanco</u> Coordinates: Letter: <u>H</u> Section <u>23</u> Township: <u>27</u> Range: <u>8</u> Or Latitude _____ Longitude _____ Pit Type: Denydrator ☒ Location Drip: ☒ Line Drip: _____ Other: _____ Site Assessment Date: <u>5/27/94</u> Area: <u>13</u> Run: <u>31</u>
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside ☒ (1) Outside ☐ (2) Land Type: BLM ☒ (1) State ☐ (2) <u>Dennis L. Zant</u> ☒ (3) DEPUTY OIL & GAS INSPECTOR Depth to Groundwater Less Than 50 Feet (20 points) ☒ (1) 50 Ft to 99 Ft (10 points) ☐ (2) Greater Than 100 Ft (0 points) ☐ (3) Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) ☒ (1) 200 Ft to 1000 Ft (10 points) ☐ (2) Greater Than 1000 Ft (0 points) ☐ (3) Name of Surface Water Body <u>Smith Canyon</u> (Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream ☐ (1) < 100' (Navajo Pits Only) ☐ (2) > 100' TOTAL HAZARD RANKING SCORE: <u>40</u> POINTS
REMARKS	Remarks : <u>Redlined Vln. - Inside</u> <u>1 Pit. Will close. Pit Dry</u>

DHS/DA/...

ORIGINAL PIT LOCATION	ORIGINAL PIT LOCATION Original Pit : a) Degrees from North <u>34°</u> Footage from Wellhead <u>103'</u> b) Length : <u>16'</u> Width : <u>16'</u> Depth : <u>2'</u>
REMARKS	Remarks : <u>Pictures of 1031 (1-4) roll 1</u> <u>Dump Truck</u>
	Completed By: <u>Cory Chan</u> Signature <u>5/27/94</u> Date

--	--	--

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	FIELD OBSERVATIONS	CLOSURE	REMARKS
Meter: <u>72368</u> Location: <u>Marron Fed #5</u> Coordinates: Letter: <u>H</u> Section <u>23</u> Township: <u>27</u> Range: <u>8</u> Or Latitude _____ Longitude _____ Date Started : <u>6/9/94</u> Area: <u>13</u> Run: <u>31</u>	Sample Number(s): <u>4P28</u> Sample Depth: <u>12</u> Feet Final PID Reading <u>0 ppm</u> PID Reading Depth <u>12</u> Feet Yes No Groundwater Encountered ☐ (1) ☒ (2) Approximate Depth _____ Feet	Remediation Method : Excavation ☐ (1) Approx. Cubic Yards <u>0</u> Onsite Bioremediation ☐ (2) Backfill Pit Without Excavation ☒ (3) Soil Disposition: Envirotech ☐ (1) ☐ (3) Tierra Other Facility ☐ (2) Name: _____ Pit Closure Date: <u>6/9/94</u> Pit Closed By: <u>BEI</u>	Remarks : <u>Dug test hole to 12' took VG Sample</u> <u>meter read 0 ppm at 72". closed pit</u>
Signature of Specialist: <u>James J. [Signature]</u>			



FIELD SERVICES LABORATORY
ANALYTICAL REPORT
PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab ID
SAMPLE NUMBER:	KOR 6-10-94 JP 28 JP 28	945408
MTR CODE SITE NAME:	72368	N/A
SAMPLE DATE TIME (Hrs):	6-9-94	1200
SAMPLED BY:	N/A	
DATE OF TPH EXT. ANAL.:	6/10/94	6/10/94
DATE OF BTEX EXT. ANAL.:	6/15/94	6/17/94
TYPE DESCRIPTION:	VG	Brown fine sand

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE	<0.025	MG/KG	1			
TOLUENE	<0.025	MG/KG	1			
ETHYL BENZENE	<0.025	MG/KG	1			
TOTAL XYLENES	0.026 0.026	MG/KG	1			
TOTAL BTEX	0.101	MG/KG				
TPH (418.1)	<10	MG/KG			2.00	28
HEADSPACE PID	0	PPM				
PERCENT SOLIDS	88.1 94.7	%				

TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at 98 % for this sample All QA/QC was acceptable.

Narrative:

ATI Results attached.

DF = Dilution Factor Used

DLP

7/17/94



Analytical **Technologies**, Inc.

2709-D Pan American Freeway NE, Albuquerque, NM 87107
Phone (505) 344-3777 FAX (505) 344-4419

ATI I.D. 406351

June 21, 1994

El Paso Natural Gas Company
P.O. Box 4990
Farmington, NM 87499

Project Name/Number: PIT CLOSURE 24324

Attention: John Lambdin

On **06/14/94**, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze **non-aqueous** samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.

If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.

Letitia Krakowski, Ph.D.
Project Manager

H. Mitchell Rubenstein, Ph.D.
Laboratory Manager

MR:jd

Enclosure

GAS CHROMATOGRAPHY RESULTS

TEST : BTEX (EPA 8020)
 CLIENT : EL PASO NATURAL GAS CO. ATI I.D.: 406351
 PROJECT # : 24324
 PROJECT NAME : PIT CLOSURE

SAMPLE ID. #	CLIENT I.D.	MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
19	945406	NON-AQ	06/09/94	06/15/94	06/17/94	1
20	945407	NON-AQ	06/09/94	06/15/94	06/17/94	5
21	945408	NON-AQ	06/09/94	06/15/94	06/17/94	1

PARAMETER	UNITS	19	20	21
BENZENE	MG/KG	<0.025	<0.12	<0.025
TOLUENE	MG/KG	0.051	<0.12	<0.025
ETHYLBENZENE	MG/KG	<0.025	2.3	<0.025
TOTAL XYLENES	MG/KG	0.097	18	0.026

SURROGATE:

BROMOFLUOROBENZENE (%) 92 37 98