

Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 077952

Unit J. C. Gordon

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 19, 1951

Well No. 1 is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 24

NE 1/4 NE 1/4 Sec. 24 27N 10E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Fulcher-Kutz (For Ext.) San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6540 ft. Ground

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded with Rotary Tools 4-17-51
Set 105 feet 9-5/8" O.D. 40# 8 rd. thd. sals. casing cemented with 60 sacks.
Tested with 800# for 30 min. with no drop in pressure before drilling Plug.
Tested with 500# for 30 min. with no drop in pressure after drilling Plug.
Drilling 254 feet, sand & shale 4-19-51

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ryrd-Frost, Inc.

Address P.O. Box 911

Durango, Colorado

By John Carothers
John Carothers
Title Dist. Office Mgr.