



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa FeLease No. L.L. 01163Unit Gentle #3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>Production 1</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
JUL 26 1956
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Gentle #3June 25,19 56Well No. 1 is located 990 ft. from [S] line and 1250 ft. from [W] line of sec. 1534 1/4 Section 15
(1/4 Sec. and Sec. No.)77N
(Twp.)SW
(Range)R.R.P.M.
(Meridian)South Blanco
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6235 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

San 7 1/2 in. (2324' 0" 5-1/2" O.D. casing - set at 2335'.
Cemented with 150 lbs. reg. cement.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AGLIZ OIL COMPANYAddress Box 426Farmington, New MexicoBy J. E. CooperTitle District Foreman

