Form	9-331
(May	1963)

UNITED STATES UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on re-

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY

SHNDRY	NOTICES	V VID	REPORTS	\triangle	14/61	
SOLINGE	MOHCE?	ANU	KEPORIS	ON	WFI	ς

(Do not use this form for proposals to drill or to deepen or plug back to a differ

077974

Use "APPLICATION FOR PERMIT-" for such proposals.)	
OH WELL OTHER	7. UNIT AGREEMENT NAME
Tenneco Oil Company	8. FARM OR LEASE NAME
1360 Lincoln, Suite 1200, Denver, Colorado 80203	Lodewick 9. WELL NO.
. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
910' FSL and 790' FWL	Basin Dakota 11. spc., t., r., m., or blk. and survey or area

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6620' DF

Sec. 18, T27N, R9W 12. COUNTY OR PARISH 13. STATE San Juan New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

01	TCE OF 15	STENTION TO:			SUBSEQUENT	REPORT OF:	
TEST WATER SHUT-OFF		PULL OR ALTER CASING]		۳	
FRACTURE TREAT		MULTIPLE COMPLETE			WATER SHUT-OFF	REPAIRING WELL	X
SHOOT OR ACIDIZE					FRACTURE TREATMENT	ALTERING CASING	
		ABANDON*			SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS			(Other)		
(Other)					(Note: Report results of r Completion or Recompletion	nultiple completion on Well	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1. MIRUPU. pulled tubing pump 1-8-75
- Set BP @ 6342.
- 3. Tested csg & located hole @ 4393-4595.
- Set pkr @ 3935. Squeezed with 300 sacks Class A cement.
- Pulled tbg and pkr. and drilled out cement. Pressure tested csg. to 500 lbs for 0.K.
- Pulled BP and cleaned out hole. 6.
- Ran tbg. w/pkr. and set 0 6871. Treated with 1000 gal. 28% acid, 1000 gal 15% acid, 22 gal Al70 inhibitor, 22 gal F-75 surfactant. 750 lb 1227 plug. Total 300 bbls acid w/32 bbl fresh wtr. flush. AIR 2 3/4 bpm.
- Swabbing well to clean up.
- 9. Clean up area.



DEC 2 3 1975 U. S. CECH COLONE, SURVEY

SIGNED (This space for Federal or State office use)	Production Clerk	DATE 12/16/73
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE