UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry No	tices and Reports on We	ells		
1. Type of Well	L	REGEIVED MAY - 4 1994	6. I	ease Numbe F-077596 f Indian, ribe Name	All. or
PO Box 4289	none No. of Opera Farmington, NM	I 87499 (505) 326-9700	8. W M 9. A — 10. F	ell Name & orris #1 PI Well No ield and P ic.Cliffs ounty and	Number .
Type of Subr _x_ Noti Subs	OPRIATE BOX TO IN mission ce of Intent equent Report 1 Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other	CE, REPO ction Chan New Non- Wate	ORT, OTHER Age of Plan Constructi Routine Fr er Shut off version to	DATA s on acturing
It is requested	existing pipeline pressure. quantities. However, it car currently evaluating option (GCNM/EPNG). The wellt pressure (150/150 psi, resp	ts present condition one year. It is a Should line pressures drop sufficient not produce at a rate sufficient to just to lower line pressure in general wore is mechanically sound, as indicated in the pressure of the present of the	ntly, the well istify wellhe ith the opera ated by rela essure for th	I would produce in ad compression. ator of the gather tionship between the area (150 psi).	in economic We are ring system tubing/casin . A
14. Thereby		foregoing is true and			
Signed Jaggy	<i>y</i> • -	(SBD) Title Regulatory A			22/94
APPROVED BY	r Federal or Stat	te Office use)Title		Date H O V E	
	•	•		25 4	