

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 90 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Alamogordo

Lease No. 377382

Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	OIL CON	DIS
NOTICE OF INTENTION TO CHANGE PLANS.....	X	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....		
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....		
NOTICE OF INTENTION TO ABANDON WELL.....				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farmington, New Mexico, October 1, 1951

Well No. F-1 is located 1450 ft. from IN line and 1450 ft. from E line of sec. 16

Section 16 (1/4 Sec. and Sec. No.) F-1-8 (Twp.) 8-12-8 (Range) 23-7 (Meridian)
Fulcher Butte (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5015 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Stanolind Oil and Gas Company is taking over operation of above well, effective October 1, 1951.

Effective that date well is to be known as Stanolind's O. I. Dargrave "F" No. 1.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box 487

Farmington, New Mexico

By [Signature]

Title Production Foreman

Land Office
License No.
Unit

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NOV 3 1951
RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER STRUCTURE
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR REPAIR
NOTICE OF INTENTION TO TEST WATER QUALITY	SUBSEQUENT REPORT OF ALTERATION OF Casing
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REPAIR WORK
NOTICE OF INTENTION TO SHOOT OR REPAIR WELL	SUBSEQUENT REPORT OF REPAIR WORK
NOTICE OF INTENTION TO FILL OR STOP CASING	SUBSEQUENT REPORT OF REPAIR WORK
NOTICE OF INTENTION TO RABBIT WORK	SUBSEQUENT REPORT OF REPAIR WORK

(INDICATE ABOVE BY CHECKING IN THE SPACE PROVIDED FOR EACH NOTICE OF OTHER DATA)

1

is to be used from 2 line and 3 line of section

(Name)
(Address)
(City)
(State)
(Country)

The elevation of the drilled floor above sea level is

DETAILS OF WORK

(Give names of and reported depths of objectives and depths of proposed and completed work)

I understand that this plan of work may receive approval from the Geological Survey, and hereby agree to the

Company

Address

By

The

--	--	--