

Salta 78

(SUBMIT IN TRIPLICATE)

Land Office **079115**

Lease **Kilon M. Toskin**

Unit

RECEIVED

JAN 22 1951

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

| | |
|---|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 19

51

19

13

Well No. **2** is located **1650** ft. from **N** line and **990** ft. from **E** line of sec. **13**

Range, Sec 13

27

12W

N.M. 2743

W. Rutz Canyon

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

On January 19, 1951 mudded 7" casing at 1702 ft.
Obtained 100% water shut off. Tested by bailing.



Approval of this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

By **L. JOHNSON**

Geologist

W. Rutz Canyon, San Juan, New Mexico

Checked

By **W. Rutz Canyon, San Juan, New Mexico**

(Initials)