



Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 93300
Unit Florencia

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | Water Fracture <input checked="" type="checkbox"/> |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 20, 1956

Well No. C-2 is located 1520 ft. from N line and 590 ft. from W line of sec. 1.

N section 10 27N 0N RMPH
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

So. Placer P.C. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6057 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-25-56 Total depth 2174', C.O.T.D. 2146'.
Water fractured Pictured Cliff perforated intervals 2095' - 2130' with 4 shots/ft.
with 35,753 allons water and 60,000# sand. Breakdown pressure 2700#, maximum
pressure 1500#, average treating pressure 1400#. Injection rate 43 bbls./min.
Flush 2184 allons. Natural gas none.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Samuel W. Wolsch

Title Petroleum Engineer



1