


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. S. F. 078357
Unit Marshall "A"



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF PRODUCTION
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall "A"

May 7, 1956


Well No. 3 is located 1380 ft. from N line and 1650 ft. from E line of sec. 15

NE 1/4 Section 15 27N 9W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Alamo San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6132 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of pipe, casing, and all other important proposed work; show all cementing jobs, cementing points, and all other important proposed work)



Drilled to 2245' - ran 70 joints 5-1/2" casing,
set at 2235' & cemented with 150 sks. reg. cement.
Tested casing with 500# pressure for 30 min.
Pressure held.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Address Box 426,

Farmington, New Mexico

By P. E. Cooper

Title District Foreman

1000000

...and the

Journal of Management Education 30(6)

