

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. S. F. 078357
Unit Marshall "A"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Report of Perforations & sand-free X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall "A"

May 10, 19**56**

Well No. 3 is located 1380 ft. from N line and 1650 ft. from E line of sec. 15

NE 1/4 Section 15 27N 9W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Planco San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6132 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated 5-1/2" casing with 4 bullets per foot from 2136' to 2195' for a total of 236 shots. Well showed very small amount gas after perforating.

Treated perforations with 60,000# sand & 47,250 gallons water, using 55 bbls water to flush. Breakdown 1600# - treating 1600#. Inj. rate 51.9 bbls/min., time of treatment 24 min.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SHELLY OIL COMPANY
Address Box 426,
Farmington, New Mexico

By P. E. Cooper
Title District Foreman

