

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 3. 7. 07337  
Unit Marshall #1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>PRODUCTION</u> .....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall #1

Nov 14, 19 56

Well No. 4 is located 1370 ft. from N line and 1290 ft. from E line of sec 15

NE 1/4 Section 15

(1/4 Sec. and Sec. No.)

27N

(Twp.)

9E

(Range)

(Meridian)

South Blanco

(Field)

San Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is 6112 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 68 jts. 5-1/2" OD 14.6 lb-55 casing, set at 2200' and cemented with 150 mcs. regular cement. Tested with 500# pressure for 30 minutes. Pressure held.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GRELLY OIL COMPANY

Address P. O. Box 426,

Farmington, New Mexico

By J. E. Cooper

Title District Foreman