



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Marshall
Lease No. 078357
Unit Marshall

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall "A"

April 27, 1951

Well No. 2 is located 1010 ft. from N line and 1315 ft. from E line of sec. 14

14 (Sec. and Sec. No.) 27N (Twp.) 7E (Range) 7E (Meridian)

South Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6059 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Completed: 2:00 A.M. April 25, 1950.

Run 7 jts. (133') 8-5/8" casing, set at 143' & cemented with 150 lbs. reg. cement. Cement circulated. Tested with 500 pressure. Pressure held.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Marshall Oil Company

Address P.O. Box 426,

Marshall, New Mexico

By F. E. T. Cooper

Title District Engineer