

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. S. F. 078357  
Unit Marshall #2

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	<u>Report of perforations &amp; water frac</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Marshall #2 April 30, 1956

Well No. 1 is located 340 ft. from N line and 830 ft. from W line of sec. 14

NW 1/4-Section 14 27N 7W N. H. P. M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
South Blanco San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6112 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated 2127' - 2187' w/4-9/16 Schlumberger bullets per ft. for total of 240 shots. Very small show gas after perforating.

Sand-water frac with 70,000# sand & 37,254 gallons water - 63,546 gallons in overall treatment. 22 press. 2600# - max. treating 1100#-min. 800#. Inj. rate 32 bbls/min. Time of treatment 39 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SEELY OIL COMPANY

Address P. O. Box 426,  
Hartington, New Mexico

By P. E. Cooper

Title District Foreman