


STATE OF NEW MEXICO
**OIL CONSERVATION
 COMMISSION**
 DISTRICT NO. 3
 Phone 99 P. O. Box 697
 AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

Land Office Las Alamos
 Lease No. 27129
 Unit San Juan



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Armadillo, New Mexico, September 13 1951

Well No. 2-1 is located 490 ft. from N line and 1195 ft. from E line of sec. 14

SE 1/4 of Section 14 (1/4 Sec. and Sec. No.)
7-27-N (Twp.) R-10- (Range) T11N (Meridian)
Fulcher-Mats (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6138 ft. (M.S.L.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

All work ceased September 3, 1951.

On September 4, 1951, 1 1/2" casing was run at 101' with 300 sacks of cement. Cement circulated to surface; cement plug down at 1134'. On September 4, 1951, at 1:30 p.m. on September 5, casing and water shut-off were tested with 75 pounds pump pressure for 30 minutes. No drop in pressure resulted. Thirty-seven feet of white cement was drilled in bottom of pipe and water shut-off again tested with 75 pounds for 30 minutes. No drop in pressure during this test. No logging operations were resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Armadillo Oil and Gas Company

Address Box 467

Armadillo, New Mexico

By D. J. Spurr

Title Promotion Manager

