Form 9-331 a (March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office Santa Fe
Lease No080181
Unit B. Arbogast

SUNDRY NOTICES	AND	REPOR	IS ON	WELLS	
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPOR	T OF WATER	SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	1 11			NG OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPOR	T OF ALTERI	NG CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	i II	SUBSEQUENT REPOR	T OF REDRIL	LING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	1 11	SUBSEQUENT REPOR	T OF ABANDO	NMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	1 1	SUPPLEMENTARY WI	ELL HISTORY.		
NOTICE OF INTENTION TO ABANDON WELL	1 1	*********			
(INDICATE ABOVE BY CHECK M				DATA)	
		Dec	29,	,	19_149
Well No. 1 is located 990 ft.	. from	line and _9	90 ft. fr	om W line of sec.	13
Section 13 278 (1/4 Sec, and Sec. No.) (Twp.)	10 [#]	NAPH	(Meridian)	-	
**-	-				
Kuts Canon S	unty or Sub	division)		(State or Territory)	
•					
The elevation of the derrick floor above sea	a level is	s tt.			
DE	TAILS (OF WORK			
State names of and expected depths to objective sands; sho ing points, and	w sizes, wei l all other i	ights, and lengths of mportant proposed	proposed cas work)	ings; indicate mudding job	s, cemen
Drill with rotary to top of Pictu	ured Cl	iffs sand.			
Set 125 feet 9 5/8" OD 10# smls.	grade	d casing ce	mented '	to surface.	
Set 5 1/2 inch 0D 15 smls. J 55 sand comented with 100 sacks.	casing	production	string	on Pictured Cli	ffs
Complete with cable tools.					
			,		
I understand that this plan of work must receive approv	ral in writir	ng by the Geological	Survey before	re operations may be comm	aenced.
Company FOUR CORNERS OIL CORP.					
Address Box 911	·				
Durango, Colo.		Bv	н. Р.	Slagel	••····································
		Title	Dist.	Suot.	
		1 1616			