۵		
1		
1		
		1
1	:	

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	udget Bureau No. pproval expires 12	
Land Offic	. Şanta	Fe
Lease No.	3¥079115	
11-14		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF	NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ALTERING CASING
--	--	--------------------------------------

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	Septem	aber 29,	, 19 <u>60</u>
Randell  Well No is located	1 790 ft. from XX Spline and 27 North 12 rest	990 ft. from W line	of leg 113
N#/4 Sect. 13	27 North 12 mest	MAPM	Million /
Undesignated Dakot a	(Twp.) (Range) San Juar: County	(Meridian) New Nexico	00110 330
(Field) ground	(County or Subdivision)	(State or Territo	ory)
The elevation of the derrick f	loor above sea level is 6049	ft.	
			. *

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 42" OD new electric weld (9.5% & 11.6%) caxing. Set & comented @ 6310' w/ 250 sx 50-50 posaix cement. Bet a DV tool > 1783' w/ HoWCo basket below and comented w/ 75 sx 50-50 pozaix. Temperature survey indicated the bottom stage of cement filled to 5100'. Pressured up an DV tool before and after drilling w/ 800 psi and there was no leakage. Used 150' of scratch rs, and put centralizers on the bottom six joints as well as on the joints above and below the DV tool.

	W. A. MONCHI F, JR.	ing by the Geological Survey before operations may be commenced.
Company Address	c/o Lawrence E. Brock	7 3 Band
P. U. Box 2045	P. O. Box 2045	By Lawrence E. Brock
Parmington, New Mexico		Title AGULT - New Mexico