



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe, N. Mex.**

Lease No. **SF 078935**

Unit **Campbell Federal Dakota**
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 27, 19 **62**

Well No. **1** is located **990** ft. from **N** line and **1650** ft. from **E** line of sec. **15**

NE/4, Sec. 15

(1/4 Sec. and Sec. No.)

T27N

(Twp.)

R12W

(Range)

NMPM

(Meridian)

Basin Dakota

(Field)

San Juan

(County or Subdivision)

N. Mex.

(State or Territory)

The elevation of the derrick floor above sea level is **5902** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Spudded at 3 A.M., 7-22-62. Set 8-5/8", 24#, J-55 casing at 123' & cemented w/ 100 sks. Neat w/ 3% CaCl. Cement circulated. WOC 24 hrs. Tested csg. w/ 600# for 30 mins., no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Tidewater Oil Company**

Address **Box 547**

Hobbs, N. Mex.

Original Signed By

C. L. WADE

By

Area Supt.

Title