COPY FOR STATE OF NEW MEXICO OIL CONSERVATION SUBMIT IN TRIPLICATE DISTRICT OFFICE

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Santa	Fe	
Lease No.	02988		

Unit

Whitlex

SUNDRY NOTICES AND REPORTS ON WE

OIL CON.

NOTICE OF INTENTION TO DRILL.	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		N.	ny 12,	, 19 <u>52</u>	
Well No. 1-A Whitlew locat	ted 990 ft.	from [N] line an	d 1650 ft. from	w line of sec. 17	-
NE_4^1 NN_7^1 Sec. 17	2 7N	117	N.MP.M.		
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
West Kutz Canyon	San Ju	an County	New	Mexico	
(Field)	(Com	nty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 6163 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

> Well was spudded May 5, 1952. Cemented 10-3/4" casing at 91' with 150 sacks. Tested casing for 30 minutes with 500# pressure with no leaks.

> Drilled cement plug May 6, 1952, tested for 30 minutes with 500# pressure with no drop in pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	SOUTHERN UNION CAS COMPANY	
Address	110h Burt Building	
***************************************	Dallas, Texas	By Haral Jacque
***************************************		Title Drilling Superintendent