

APPROVED

JUN 19 1956

Budget Bureau No. 42-R359.4.
Approval expires 12-31-60.Form 9-3312
(April 1952) (Orig. and J. W. LONG

(SUBMIT IN TRIPLICATE)

Indian Agency _____

ACTING DISTRICT ENGINEER

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Name Allotted _____

Allottee Billie FlatauLease No. 2-140-2nd, 044

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
MAY 24 1956

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Billie FlatauMay 24, 1956Well No. 2 is located 990 ft. from S line and 990 ft. from E line of sec. 20SW/4 Section 20
(1/4 Sec. and Sec. No.)SW
(Twp.)SW
(Range)N. H. P. N.
(Middian)South Florida
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 4043 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Run 42 lbs. 5-1/2" 11' casing, set at 2200' and cemented with 100 sacks regular cement. Started casing with 500' pressure for 30 minutes - hold day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company SHULTZ OIL COMPANYAddress Box 434Farmington, New MexicoBy J. W. LongTitle District Engineer

