


(SUBMIT IN TRIPLICATE)

Indian Agency .....



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Survey No. ~~1190~~  
Allottee ~~1190~~  
Lease No. ~~1190~~

# SUNDRY NOTICES AND REPORTS ON WELLS

|  |   |
|--|---|
| NOTICE OF INTENTION TO DRILL.....                  | SUBSEQUENT REPORT OF WATER SHUT-OFF.....        |
| NOTICE OF INTENTION TO CHANGE PLANS.....           | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....    | SUBSEQUENT REPORT OF ALTERING CASING.....       |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....  |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....       | SUBSEQUENT REPORT OF ABANDONMENT.....           |
| NOTICE OF INTENTION TO PULL OR ALTER CASING.....   | SUPPLEMENTARY WELL HISTORY.....                 |
| NOTICE OF INTENTION TO ABANDON WELL.....           |   |

RECEIVED  
AUG 10 1956  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 3 is located 1190 ft. from (S) line and 1190 ft. from (E) line of sec. 12  
1190 (wp.) (Range) (Section)  
South: 11900 - P.O. (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 4 jobs. (122') 2-5/8" casing - set at 135'.  
Cemented with 150 lbs. cement. Circulated.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Shelly Oil Company  
Address Box 126  
Farmington, New Mexico

By P. E. Cooper  
Title District Foreman