


Land Office Santa Fe
Lease No. 070673
Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 1, 1955

Well No. R & J #15 located 1100 ft. from N line and 800 ft. from E line of sec. 10
32/4, sec. 10 T 27 N R 11 W N M P M
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcat San Juan N.M.
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6214 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Casing sundry:

8-5/8" surface casing - 90' with 50 sacks cement
5-1/2" producing casing - 2033' with 200 sacks cement



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company R & J Drilling Co., Inc.

Address 250 E. 57th St.
New York 19, N.Y.

By R. Schwartz

Title office mgr.