

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

New Mexico Allotted

Allottee Hollis FlatoreLease No. I-149-Sub. 8464

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|---|----------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF <u>PRODUCTION</u> | <u>X</u> |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hollis FlatoreApril 10, 19 56Well No. 1 is located 1360 ft. from XX line and 1293 ft. from W line of sec. 10SW 1/4 Section 10
(34 Sec. and Sec. No.)27N
(Twp.)9W
(Range)N. M. P. M.
(Meridian)South Flamingo
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation 2500 above sea level is 6167 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 60 joints 5-1/2" 11# casing, set at 2214' and cemented with 150 sacks regular cement. Tested with 300# pressure held okay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANYAddress Box 424,
Farmington, New MexicoBy P. E. InspeyTitle Chief of Farming

