



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Allottee Hollie Platore
Lease No. 2-149-2nd-244

RECEIVED
MAY 29 1956
GEOLOGICAL SURVEY
NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hollie Platore

May 29, 1956

Well No. 2 is located 1650 ft. from EN line and 1650 ft. from W line of sec. 11

SW/4 Section 11
(1/4 Sec. and Sec. No.)
South Elmore
(Field)

27N 9W
(Twp.) (Range)
San Juan
(County or Subdivision)

H. M. P. M.
(Meridian)
New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6050 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 67 joints 2-1/2" 14# 2-55 casing, set at 2276' and cemented with 150 sacks regular cement. Tested casing with 500# pressure for 30 minutes - pressure held.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KELLY OIL COMPANY

Address Box 426
Farmington, New Mexico

By J. E. Cooper

Title District Foreman