



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_  
Bonds Allotted \_\_\_\_\_  
Allottee **Skelly Platoon**  
Lease No. **2-249-2nd, 2444**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<b>Sand-Gravel &amp; Perforation</b>	<b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Skelly Platoon**

**June 4,** 19**56**

Well No. **3** is located **1450** ft. from **XX** line and **1450** ft. from **W** line of sec. **11**

**SW 1/4 Section 11**  
(1/4 Sec. and Sec. No.)

**R7E**  
(Twp.)

**T4N**  
(Range)

**T. 4N. R. 7E**  
(Meridian)

**South Platoon**  
(Field)

**San Juan**  
(County or Subdivision)

**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **4050** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Treated with 40,000/ sand, 54,600 gals. water. Break-down 2400/ - max. 2450/ - min. 1350/. Inj. rate 97 mins. per minute. Time of treatment, 24 minutes.

Perforated from 2145' to 2140' w/ 1.5/32 bullets per foot for total of 248 shots.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **SKELLY OIL COMPANY**

Address **Box 486**

**Farmington, New Mexico**

By **J. E. Cooper**

Title **District Foreman**