



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-R358.3.
Approval expires 12-31-55.

Land Office SANTA FE

Lease No. 512354-A

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

H. K. Riddle Unit II

Well No. 1 is located 930 ft. from N line and 1650 ft. from E line of sec. 9

NE 1/4 Sec 9

(1/4 Sec. and Sec. No.)

27N

(Twp.)

12W

(Range)

100W

(Meridian)

to Blanco P.C.

(Field)

San Juan County

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 6300 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9-5/8", 30# casing was run and set at 93.50 with 70 sacks. 7-7/8" hole was drilled through Pictured Cliffs to total depth of 2370' and 3-1/2" run to 2320' and cemented with 100 sacks. Well was cleaned out and modified by Rocco with 20,000# sand.

Per test natural 91 MCFD

Per test after treatment 3610 MCFD, after SI period of 7 days.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company Texas Gas Transmission Co

Address Box 1772

Casper, Wyoming

Original Signed By:
PAT LAY

By

Pat Lay

Title District Superintendent