

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 27-077674
Unit San Juan

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	XX
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 13-0 is located 1010 ft. from N line and 010 ft. from E line of sec. 12
Section 12 (1/4 Sec. and Sec. No.) T-27N (Twp.) R-10W (Range) T.N.T.M. (Meridian)
Fulcher Katz P.O. San Juan New Mexico
Wildcat-Platte (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6349 ft. C.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 7/19/60
 Landed 10 jts., 303' of 13 3/8" casing, at 314' with 27% solids cement
 Tested casing with 500 pressure for 30 minutes.
 No leaks.
 Drilled cement plug 7/21/60
 Tested with 500 pressure for 30 minutes.
 No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Artes Oil & Gas Company
 Address Drawer 5770,
Farmington, New Mexico
 ORIGINAL SIGNED BY JOE C. SALMON
 By Joe C. Salmon
 Title District Superintendent



--	--	--	--