



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078902  
Unit Sarah Lilly "A"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY..... <b>X</b>
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER)

**RECEIVED**

Farmington, New Mexico JUN 4 1956  
U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO  
line of sec. 9

Well No. 1 is located 990 ft. from {N} line and 990 ft. from {S} line of sec. 9  
NE/4 of Section 9 T-27-W R-12-W NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
West Kats-Pictured Cliffs San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5794 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This form is filed to change the name of the above lease and well from  
Sarah Lilly "A" No. 1 to 'GALLEGOS CANYON UNIT NO. 79'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE NEW MEXICO OIL COMPANY  
Address FARMINGTON, NEW MEXICO  
By L. O. Sperry  
Title Field Superintendent

RECEIVED

U. S. DEPARTMENT OF AGRICULTURE  
WASHINGTON, D. C.