(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Sente Pe
Lease No.	079116

160 Unit-

(State or Territory)

IAN 2 2 1952

SUNDRY NOTICES AND REPORTS ON WELLS JAM COM.		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
(INDICATE ABOVE BY CHECK MAR	K NATURE OF REPORT, NOTICE, OR OTHER DATA)	

January 17 . 19 52 Well No. ____ is located _____ ft. from N line and _____ ft. from W line of sec. ______ 11 Sec. 11 (Meridian) (14 Sec. and Sec. No.) New Mexico San Jaan et Date Compon

(Field) The elevation the day the above sea level is _\$652.5t.

DETAILS OF WORK

(County or Subdivision)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Tested surface pipe 30 min. 500f no pressure drop.

Drilled plug 1580, drilled to 1585, tosted & hrw., bailing no water.

Shot well Jamery 3, 1952, 210 qte selidified mitro by Atlas Elyserine Co. Shot temped graval and Calseal. Well tested 1,000 MCF before shot.

1642 1º line pipe set in well. Christmas tree installed. Well completed January 5, 1952.

I understand that this plan of work	must receive approval in t	writing by the Geological Survey before operations may be commenced.
Company	D. Hancock &	Conpany, Ltd.
Address 916 Eirby	Building	
Balles, 1	least .	By C. Fr. Theres
		Title Assistant Superintendent