

District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer

District III

1000 Rio Chama Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 3/9/94)

SEP 26 1997

PIT REMEDIATION AND CLOSURE REPORT

Operator: LOUIS DREYFUS NATURAL GAS

Telephone: (505) 885-1313

Address: P.O. BOX 370, CARLSBAD, NM 88211

Facility Or: MUDGE "A" #6

Well Name

Location: Unit or Qtr/Qtr Sec NW/NW Sec 7 T27N R11W County SAN JUAN

Pit Type: Separator XX Dehydrator Other

Land Type: BLM XX, State , Fee , Other

Pit Location: Pit dimensions: length 32, width 35, depth 25
(Attach diagram)

Reference: wellhead , other See Attached

Footage from reference:

Direction from reference: Degrees East North
of
 West South

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

RECEIVED
SEP 24 1997

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 Points) 10

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: 03/05/96 Date Completed: 03/08/96
Remediation Method: Excavation X Approx. cubic yards 1037

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Location: Onsite XX Offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description of Remediation Action: _____
CONTAMINATION WAS REMEDIATED BY DILUTION AND AERATION.

Ground Water Encountered: No _____ Yes _____ Depth _____

Final Pit:
Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample location See Attached

Sample depth 25

Sample date 03/06/96 Sample time 01:00:00

Sample Results

Benzene (ppm) 5

Total BTEX (ppm) 25

Field headspace (ppm) _____

TPH 18

Ground Water Sample: Yes _____ No XX (If yes, attach sample results)

I HEREBY CERTIFY THAT INFORMATION ABOVE IS TRUE AND COMPLETE
TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 09/12/96

SIGNATURE

Tommy H. Arnwine

PRINTED NAME Tommy H. Arnwine, A.S.P.
AND TITLE Environmental & Safety Director

PIT CLOSURE SAMPLING REPORT

OPERATOR LOUIS DREYFUS NATURAL GAS

ADDRESS: P.O. BOX 370 CARLSBAD, NM 88211

WELL NAME: MUDGE "A" #6

PIT TYPE: SEPARATOR LEGALS: NW/NW SEC.7 T27N R11W

CONFIRMATION SAMPLES

WALL	DEPTH	TPH	BENZENE	BTEX
NORTH	25'	16	4.4	28.7
SOUTH	25'	9	2.7	21.0
EAST	25'	22	4.9	38.6
WEST	25'	12	3.2	25.4
BOTTOM	25'	18	4.8	24.8

REMEDIATION SAMPLES

SAMPLE	TPH	BENZENE	BTEX	SAMPLE	TPH	BENZENE	BTEX
1	12	<.1	<.1	17			
2	16	<.1	<.1	18			
3	25	<.1	<.1	19			
4				20			
5				21			
6				22			
7				23			
8				24			
9				25			
10				26			
11		3		27			
12				28			
13				29			
14				30			
15				31			
16				32			


LOUIS DREYFUS NATURAL GAS

MUDGE A #6

WELLHEAD



30' 110° SE



SEPARATOR PIT