

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **SF**  
Lease No. **078872-A**  
Unit **Frontier**

RECEIVED

APR 8 1959

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<b>Sandoli Frac.</b>	<b>X</b>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 2, 1959

Well No. **2-B** is located **790** ft. from **N** line and **790** ft. from **W** line of sec. **9**

**NW NW/4 Sec. 9** **27N** **11W** **NMPM**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

**Undesignated Dakota**

**San Juan**

**New Mexico**

**Undesignated Gallup (Field)**

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is **6171** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**3-25-59 Total Depth 6719'. Clean Out Total Depth 6600'.**

**Sandoli fractured Dakota perforated intervals 6506'-6550' (Perf. 4 sh./ft.) with 36,624 gals. oil & 45,000# sand. BDP--2300#, MTP--2300#, ATP--2250#. IR--52.0 bbls./min. Flush 11,350 gals. Dropped 60 balls twice.**

**3-29-59 Total Depth 6719'. Temporary bridge plug at 6441'.**

**Sandoli fractured Gallup perforated intervals 5854'-5878' (Perf. 4 sh./ft.) with 35,700 gals. oil & 45,000# sand. BDP--2850#, MTP--2200#, ATP--1800#. IR--62.2 bbls./min. Flush 10,080 gals. Dropped 32 balls twice.**

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1565**

**Farmington, New Mexico**

ORIGINAL SIGNED BY: **J. SEPH E. KREGER**

By \_\_\_\_\_

Title **Petroleum Engineer**