

1--9-61

F. Loc. 1070/S; 1650/W Elev. Spd. Comp. TD PB
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del.

TOPS		NITD	Well Log	TEST							DATA
		X		Schd.	PC	Q	PW	PD	D	Ref. No.	
Kirtland	700	C-102	Plat X								
Fruitland		C-103	Electric Log								
Pictured Cliffs	167	C-104	C-110								
Cliff House			C-122								
Manefee		Ditr	Dfa								
Point Lookout		Datr	Dac								
Manaos		Remarks									
Gallup		P.S.A. at depth of 2992' after joint of surface pipe dropped in hole 1-7-66 W 320.72									
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											

P
o
l

Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec. |
 Basin Dakota Co. SJ S 1 T 27N R 11W U N Oper Pan American Les. E. H. Pipkin No. 8